

WM-11-02
BURLINGTON
A 210702-

1982 08 19

Mr. D. J. Corbett
Waste Disposal Engineer
Public Works Department
Regional Municipality of Halton
P.O. Box 7000
1151 Bronte Road
Oakville, Ontario
L6J 6E1


Dear Mr. Corbett:

Re: Region of Halton Landfill Sites -
Oakville, Burlington

Attached are recent site inspection reports made by Mr. H. Paar of this office. Please note the comments contained in this report.

If there are any enquiries regarding the contents of these reports, please do not hesitate to contact this office.

Yours truly,



G. L. McCarty, P. Eng.
Sr. Environmental Officer
Municipal and Private Abatement Section

GLM/js

ATT.



Ministry
of the
Environment

Ontario

Waste Disposal Site Inspection Form

FILE No.

A 210102

DATE

August 19, 1982

Re: Burlington Landfill, Lot 4, Concession 1 & 2, City of Burlington

On August 17, 1982 the above waste disposal site was inspected by

H. Paar

when the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
9. Scavenging		X
10. Operating According to Conditions on Certificate of Approval	X	

	SATIS- FACTORY	UNSATIS- FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse	X	
13. Housekeeping of 1) Site	X	
2) Adjacent Property	X	
14. Working Face	X	
15. Number of Dumping Areas	--	--
16. Segregation of Refuse	--	--
17. Segregated Material Disposal	--	--
18. Rodent and Vector Control	--	--
19. Means of Controlling Litter	X	

Operation Discussed with Mr. S. Mucciarelli

(NAME)

Region of Halton

(POSITION)

COMMENTS

- Site inspection made with Mr. Mucciarelli
- Landfilling operations are being carried out in Phase I expansion area. Cover material is being obtained from the Phase II area.
- Waste disposal operations satisfactory
- Area south of the Bell Canada lines has been graded and additional cover has been placed along the east side to bring this section into the completed stage with earth cover. This area will now require a top soil cover and seeding.
- Surface drainage works are still being constructed. New stone lined ditchery has been created on the west side of the site along the on site road. This area drains surface waters toward the North Service road. Some additional works are to be completed in this section.
- Fencing (chain link) has been installed around most of the perimeter of the Phase II expansion area.

RECOMMENDATIONS

- Leachate lines, previously installed in the Phase II expansion area have been improved.
- Container area near the weigh scales has been prepared but is not operational.

H. Paar